


The Paramount Shopping Centre

Melbourne Australia


These figures are based upon hard wiring of an energy usage monitor to a single HVAC unit and are for a period of 4 days prior to cleaning of the unit and 4 days post cleaning.

1 day prior	67.103	1 day after	58.068
2 days prior	251.917	2 days after	105.998
3 days prior	240.655	3 days after	178.766
4 days prior	142.053	4 days after	179.237
	701.728		522.069



Validation of figures

Wednesday before **240.655** Wednesday after **179.237**



These figures consistently show a saving of >25%



The Paramount Shopping Centre

Melbourne Australia

Readings from Right to left

Filter 1 before 4.29 m/sec after 10.00 m/sec

Filter 2 before 4.70 m/sec after 10.00 m/sec



Filter 3 before 3.62 m/sec after 8.13 m/sec



Please note that pie chart graphs are an approximate representation based on the written figures.

Condenser 1

Before top 38.2 degree C

After 29.1 degree C

Before below 43.7 degrees C

After 36.2 degree C

Condenser 2

Before top 36.2 degree

After 27.2 degree C

Before below 58.2 degree C

After 46.1 degree C